

Unawarded MILCON

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Air Force	Tinker AFB	OK		Construct Child Development Center	May-10
Air Force	Minot AFB	ND		Construct Dormitory	May-10
Air Force	Minot AFB	ND	QJVF066016A	Repair Missile Alert Facility HVAC System (Heat Pumps)	May-10
Army	Iowa AAP	IA	72869	Ground Source Heat Pumps & Photovoltaic for Bldg 100-101	Mar-10
Army	Fort Campbell	KY	69776	Replace Air Conditioner with Ground Source Heat Pump, Efficient Boilers	Mar-10
Army	Hawthorne AD	NV	72693	Geothermal Test Wells, Phase 2	Mar-10
Army	Fort Sill	OK	72679	Solar Water Preheater	Mar-10
Army	McAlester AD	OK	74393	Family Housing Replacement Construction (6 units)	May-10
Army	Tobyhanna	PA	74519	Family Housing Replacement Construction (2 units)	May-10
Defense-Wide	USAF Academy Commissary (DECA)	CO	WP10ME01	Energy Conservation Upgrades	Sep-10
Defense-Wide	Camp Pendleton	CA	71653	Hospital Replacement	Sep-10
Defense-Wide	Fort Hood	TX	74650	Hospital Replacement Phase 1	Sep-10
Navy	MCLB Barstow	CA	P970M	Facility Energy Improvements	Mar-10
Navy	MCAS Miramar	CA	P982M	Facility Energy Improvements	Mar-10
Navy	SPAWAR San Diego	CA	P0875	Photovoltaic System	Jun-10
Navy	SPAWAR San Diego	CA	P0876	Photovoltaic System	Jun-10
Navy	Naval Station Norfolk	VA	P116	Steam Plant Area Decentralization	Jul-10
Navy	Naval Base Ventura County	CA	P0885	Wind Turbine Generation	Aug-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Army	Buckley AFB (Enclave)	CO	8990035	Boiler Replace Building 1500	Mar-10
Army	Muscatatuck Urban Training Center	IN	18080256	Replace Roof, Windows, Mechanical and Electrical Systems, and Fire Suppression System at Building 20 (Transient Training Officers Quarters)	Mar-10
Defense-Wide	WRAIR - Forest Glen	MD	83	Repair Research Labs in Building 508 - Walter Reed Army Institute of Research	Mar-10
Army	Abbeville	LA	NULL	Repair/upgrade Entire Field Maintenance Shop to Current Electrical Standards	Mar-10
Air Force	Nellis AFB	NV	RKMF080020	Repair Water Main, Tyndall Ave	Mar-10
Air Force	Nellis AFB	NV	RKMF040020	Repair Airfield Lighting Circuit Cables	Mar-10
Air Force	Vandenberg AFB	CA	XUMU051158B	Replace Water System, 30th Mission Supp Group Area	Mar-10
Air Force	Pope AFB	NC	TMKH041005	Remove Airfield Obstructions from Runway 23 Clear Zone	Mar-10
Air Force	Pope AFB	NC	TMKH071011	Airfield Rubber Removal And Striping	Mar-10
Army	Fort Polk	LA	35616	Consolidated Fuel Fac Access Road & Utilities	Mar-10
Army	West Point Mil Reservation	NY	36189	Alter Electrical System at Morgan Farms	Mar-10
Army	Fort Richardson	AK	35009	Repair and Upgrade Rail Spur	Mar-10
Army	Wheeler Army Airfield	HI	38192	Replace Building 105 HVAC System	Mar-10
Army	Fort Polk	LA	32063	Repair and Clean 22 Tactical Equipment Maintenance and Administrative Facilities	Mar-10
Army	Fort Bliss	TX	29157	Repair Tac Equip Shop 2971, Task Force Cram Elect, HVAC, Plumbing, Finishes	Mar-10
Army	Fort Bliss	TX	34288	Repair Bldg 4797 Fitness Center--HVAC & Resurface Floor	Mar-10
Army	Fort Sam Houston	TX	22243	Repair Classroom, Bldg 1396	Mar-10
Army	Fort Sam Houston	TX	25295	Barracks Bldg 904-- Replace HVAC, Plumbing, Electric, Finishes	Mar-10
Army	Fort Sam Houston	TX	38957	Repair Fire Alarm Systems, Various Buildings	Mar-10
Army	Baton Rouge	LA	NULL	Repair/upgrade Field Maintenance Shop to Current Electrical Standards	Mar-10
Army	Terre Haute	IN	18080030	Replace Roof at Readiness Center	Mar-10
Army	Muscatatuck Urban Training Center	IN	18080262	Replace Mechanical and Electrical Systems, Fire Suppression System, and Interior Finishes at Building 60 (Transient Training Battalion Headquarters)	Mar-10
Defense-Wide	Fort Rucker	AL	4	Replace All AHU, Dampers, & Bal Sys - US Army Aeromedical Research Laboratory	Mar-10
Army	Fort Lewis	WA	34158	Repair Sanitary Sewerlines - Failing Vitrified Clay Pipes	Mar-10
Army	Camp Beaugard	LA	22200903038	Repair Roof at Barracks (Bldg 1018)	Mar-10
Army	Camp Beaugard	LA	22200812092	Repair/upgrade Barracks (Bldg 1004) to Current HVAC and Electrical Standards	Mar-10
Army	Fort Dix/DRFTA	MA	DKF33000-8	Interior Repair and Alteration, Training Barracks, Building 693	Mar-10
Army	Fort Dix/DRFTA	MA	DKF33010-8	Interior Repair and Alteration, Training Barracks, Building 695	Mar-10
Army	Camp Villere	LA	22200812098	Repair/upgrade Barracks (Bldg 0404) to Current HVAC and Electrical Standards	Mar-10
Army	Fort Richardson	AK	33898	Install Parking Lights Building 1	Mar-10
Army	Fort Richardson	AK	36061	Building 470 Repair Exterior	Mar-10
Army	Fort Richardson	AK	36063	Construct Temporary Deployment Facility	Mar-10
Army	Fort Richardson	AK	35364	Install Lighting Controls Building 800	Mar-10
Army	Fort Wainwright	AK	38432	Repair/Upgrade Insulation on Steam and Condensate Lines in Multiple Buildings	Mar-10
Army	Fort Rucker	AL	34603	Construct Pavilion	Mar-10
Army	Pine Bluff Arsenal	AR	38703	Repair Building 63-200-Replace Personnel and Vehicular Doors Ammunition Facility.	Mar-10
Army	Fort Irwin	CA	20159	Construct Additional Perimeter Lights Asp - Phase 3	Mar-10
Army	Fort Irwin	CA	34632	Repair Street Lights & Install Solar Street Lights for Cantonment Area	Mar-10
Army	Fort Irwin	CA	36265	Repair Roof, Building 361, Recreation Center	Mar-10
Army	Fort Irwin	CA	39041	Repair Street Lights & Install Solar Street Lights for Cantonment Area - Phase 2	Mar-10
Army	Fort Irwin	CA	36266	Repair HVAC, Building 361, Recreation Center	Mar-10
Army	Fort Irwin	CA	37574	Construct Parking Lot Lights Building 940	Mar-10
Army	Presidio of Monterey	CA	36235	Replace Synthetic Turf at Child Development Center Building 7693	Mar-10
Army	Fort Benning	GA	38941	Repair Dining Facility Building 2895 11th Engineer-Walls, Finishes, Food Prep, Serve, Seating Area	Mar-10
Army	Fort Benning	GA	38917	Renovate - Building 2768 - 199th INF Brigade Headquarters. Repair Walls, Floors, Ceilings, Doors, Windows	Mar-10
Army	Fort Benning	GA	34525	Bridge Footing Repair, Install Curtain Wall & Remediate Stream Bed	Mar-10
Army	Fort Benning	GA	38937	Repairs to Main Post CDC Building 1366	Mar-10
Army	Schofield Barracks	HI	33807	Repair Range Roads	Mar-10
Army	Fort Polk	LA	29757	Dining Facility Building 2382, Repair Failing Electrical, Mechanical, and Fire Detection / Suppression System	Mar-10
Army	Fort Polk	LA	30647	Repair Failing HVAC, Paint & Interior Repair B 2070	Mar-10
Army	Adelphi Labs	MD	12112	Upgrade HVAC System - Building 403	Mar-10
Army	Detroit Arsenal	MI	36810	Install / Modify Barriers & Lns	Mar-10
Army	Fort Leonard Wood	MO	38854	Replace Obsolete Boilers, B-749/837	Mar-10
Army	Fort Leonard Wood	MO	36311	Upgrade Interior of Chapels, B-637/843	Mar-10
Army	Fort Leonard Wood	MO	38858	Repair leaking Boilers	Mar-10
Army	Fort Leonard Wood	MO	38851	Replace Old Am-150 Boilers, B-2030	Mar-10
Army	Fort Leonard Wood	MO	38853	Replace Sectional Hot Water Boiler, B-1000	Mar-10
Army	Fort Leonard Wood	MO	38866	Upgrade BACNET digital Controls	Mar-10
Army	Picatinny Arsenal	NJ	39008	Siding Replacement	Mar-10
Army	Picatinny Arsenal	NJ	30255	Replace Existing Service Water Line	Mar-10
Army	Picatinny Arsenal	NJ	39019	Repair Street Lights	Mar-10
Army	Picatinny Arsenal	NJ	29398	Repair/Replace Electric Heaters	Mar-10
Army	Fort Drum	NY	34780	Upgrade 3rd BCT Headquarters, P10500	Mar-10
Army	Fort Drum	NY	31874	Install Indirect Evap Cooling, P-10690	Mar-10
Army	Fort Drum	NY	34751	Repair Electrical in Barracks 3rd Bde	Mar-10
Army	Fort Drum	NY	34752	Repair Electrical in Barracks P4412	Mar-10
Army	West Point Mil Reservation	NY	38406	Storm Sewer Rehab Investigation/Design	Mar-10
Army	Carlisle Barracks	PA	34075	Repair Roof on Youth Teen Club B-637	Mar-10
Army	Carlisle Barracks	PA	34077	Repair the Roof on the Health Clinic B-450	Mar-10
Army	Carlisle Barracks	PA	34076	Repair the Roof on the Post Exchange B-844	Mar-10
Army	Letterkenny Army Depot	PA	38965	Rehabilitate Industrial Waste Collection System, Building 37 - 1	Mar-10
Army	Fort Jackson	SC	17788	Replace Heating Water Distribution from Central Plant #2 to Hospital Zone	Mar-10
Army	Fort Jackson	SC	38975	Renovate B5625 (Former Hood Street School)	Mar-10
Army	Fort Jackson	SC	30024	Repair Messers Pond Culvert	Mar-10
Army	Fort Jackson	SC	38967	Repair Failed Stormwater Systems at Strom Thurmond Blvd and Tank Hill	Mar-10
Army	Fort Jackson	SC	12224	Place Energy Management Control Systems Controls on LAN	Mar-10
Army	Fort Jackson	SC	38974	Resurface Magruder Ave	Mar-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Army	Fort Jackson	SC	7641	Replace HVAC at Building 4600	Mar-10
Army	Fort Jackson	SC	30027	Resurface Washington and Anderson Street	Mar-10
Army	Fort Jackson	SC	38971	Replace Failed Roof on B1860	Mar-10
Army	Fort Jackson	SC	32839	Renovate HVAC in Building 5975 W/New Energy Efficient Equipment	Mar-10
Army	Fort A.P. Hill	VA	38644	Replace Roof on 1690 Dining Facility Wilcox	Mar-10
Army	Fort Belvoir	VA	29225	Replace Windows/Repair Insulation, Exterior Façade, and Vapor Barrier, VOLAR Barracks, Building 2109	Mar-10
Army	Fort Belvoir	VA	35588	Replace Windows/Repair, Insulation, Exterior Façade and Vapor Barrier, VOLAR Barracks, Building 2111	Mar-10
Army	Fort Lewis	WA	34185	Repair Sidewalks in Historic Garrison Area	Mar-10
Army	Fort Lewis	WA	34162	Replace Electrical Distribution Systems in Greenwood Housing	Mar-10
Army	Fort Lewis	WA	38689	Repair Roads and Clean Roofs/Gutters	Mar-10
Army	Fort Lewis	WA	15618	Recommission Facilities	Mar-10
Army	Fort Lewis	WA	32158	Flagship Paint, Replace Carpet, Clean 593 Headquarters Facility, Fac 12235	Mar-10
Army	Fort Lewis	WA	32153	Flagship Replace Carpet and Paint Facility	Mar-10
Army	Fort Lewis	WA	32156	Flagship Paint, Replace Carpet, Clean 21 TC Co Facility, Fac 12327	Mar-10
Army	Fort Lewis	WA	32157	Flagship Paint, Replace Carpet, Clean 497 TC Co Facility, Fac 12437	Mar-10
Army	Fort Lewis	WA	32155	Flagship Paint, Replace Carpet, Clean 593 HHC Headquarters, Fac 12341	Mar-10
Army	Fort Lewis	WA	32213	Flagship Construct Showers in Latrine Areas, 3-2 SBCT, 3651, BN Headquarters	Mar-10
Army	Fort Lewis	WA	33051	Flagship Construct Showers in Latrine Areas, 3-2 SBCT, 3734, BN Headquarters	Mar-10
Army	Fort Lewis	WA	32154	Flagship Hookup Power to Lights in Parking Lot & Bball Court, 555 En BN, Fac 12663	Mar-10
Army	Fort Richardson	AK	38716	Construct Vehicle Inspection Facility at front gate	Mar-10
Army	Fort Richardson	AK	38721	Upgrade Fire Suppression System Bldg 652	Mar-10
Army	Fort Richardson	AK	38810	Repair Water Sprinkler System Bld 656	Mar-10
Army	Fort Rucker	AL	30950	HVAC Conversion - Permanent Party Barracks	Mar-10
Army	Fort Rucker	AL	34845	Repair Restrooms and Septic System Building B24207	Mar-10
Army	Pine Bluff Arsenal	AR	39326	Upgrade Electrical Service to 63 Area Buildings	Mar-10
Army	Fort Carson	CO	22214	Repair Overhead Electric Lines, 7000 Area	Mar-10
Army	Fort Carson	CO	38843	Design /Construct Headquarters Facility For 71st Explosive Ordnance Disposal Detachment	Mar-10
Army	Fort Carson	CO	38844	Design /Construct artifact storage facility for 4th Infantry Division	Mar-10
Army	Fort McNair	DC	35959	Decentralize Steam Plant McNair Bldg 34	Mar-10
Army	Fort Benning	GA	22190	Decentralize Boiler Plant, Bldg 397 (8 Stand Alone Units)	Mar-10
Army	Fort Benning	GA	38661	Pavement repairs at various locations	Mar-10
Army	Fort Benning	GA	38936	Repairs to Garrison Admin Bldg 89. Repair finishes, doors, windows, latrines, HVAC, elect	Mar-10
Army	Fort Benning	GA	39279	Replace Roof Bldg 5081	Mar-10
Army	Schofield Barracks	HI	35613	Barracks Bldgs 130 and 131--Mold/Moisture/Vapor Remediation	Mar-10
Army	Schofield Barracks	HI	38222	Install Photovoltaic system and generator set, Bradshaw Airfield	Mar-10
Army	Schofield Barracks	HI	38441	Repair Child Development Center	Mar-10
Army	Schofield Barracks	HI	38506	Pohakuloa Training Area Building 238 photovoltaic system	Mar-10
Army	Schofield Barracks	HI	38507	Pohakuloa Training Area Building 390 photovoltaic system	Mar-10
Army	Wheeler Army Airfield	HI	35282	Replace Parking Apron Concrete Sections	Mar-10
Army	Fort Riley	KS	19084	Bldg 8380 Motorpool Lighting Retrofit	Mar-10
Army	Fort Campbell	KY	34908	Repair exterior Fitness Facility	Mar-10
Army	Fort Campbell	KY	34951	Repair Admin. Facilities Bldgs 6934 and 6935--HVAC, Paint, door/window, latrines	Mar-10
Army	Natick Labs	MA	31524	Improve Exterior Lighting Illumination	Mar-10
Army	Natick Labs	MA	38763	Construct Stairs Between Boiler Plant And Rear Parking Lot	Mar-10
Army	Natick Labs	MA	38769	Repair Bldg 16 Front Wall	Mar-10
Army	Natick Labs	MA	39307	Repair/Upgrade HVAC Controls - Admin Bldg 1	Mar-10
Army	Aberdeen Proving Ground	MD	34144	Replace Carbon Filtration System, E1454	Mar-10
Army	Aberdeen Proving Ground	MD	37587	Repair Modified Record Fire Range	Mar-10
Army	Adelphi Labs	MD	37955	Replace HVAC Isolation Valves Bldg 204 3rd Floor	Mar-10
Army	Fort Meade	MD	13429	Pave Overflow Parking Lot at Bldg 909	Mar-10
Army	Detroit Arsenal	MI	36152	Replace faulty capacitor banks at electrical substations	Mar-10
Army	Detroit Arsenal	MI	36828	Renovate Conf Rooms Bldg 231	Mar-10
Army	Fort Bragg	NC	32399	4-2175 Post Office--Install ADA Ramps, Doors, Parking Sign	Mar-10
Army	Fort Bragg	NC	34729	Renovate Bldg 2-1249	Mar-10
Army	Fort Bragg	NC	38298	Repair/Replace Failed and Failing Mechanical Piping/Equipment DFAC, Bldg. M-4234,	Mar-10
Army	Fort Bragg	NC	38606	Renovate Fire Station No. 1 Building: 6-9572	Mar-10
Army	Watervliet Arsenal	NY	39302	Replace Woodblock Floor, Bldg 135, Bays C18-C25	Mar-10
Army	Fort Sill	OK	19306	Repair Ketch Lake Dam and Upper Canyon Dam	Mar-10
Army	Fort Sill	OK	38098	Bldg 2281-Install Electrical Equipment	Mar-10
Army	Fort Sill	OK	38169	Bldg 730 Paint Exterior	Mar-10
Army	McAlester Army Ammunition Plant	OK	23807	Replace Water Distribution Lines to Ammo Production Area	Mar-10
Army	Toboyhanna Army Depot	PA	39335	Repair Bathrooms(S) On Second Floor Bldg 230	Mar-10
Army	Toboyhanna Army Depot	PA	39387	Southwest Quadrant Depot Paving	Mar-10
Army	Toboyhanna Army Depot	PA	39388	East Sector Pavement Replacement	Mar-10
Army	Toboyhanna Army Depot	PA	39389	Central Region Paving Renovation	Mar-10
Army	Fort Jackson	SC	13825	Construct Small Childcare Facility	Mar-10
Army	Fort Jackson	SC	38809	Central Energy Plant Distribution Repairs (B11000 Feeder)	Mar-10
Army	Fort Jackson	SC	38978	Repair Failed Sewer Lift Station (Tank Hill Service Area)	Mar-10
Army	Fort Jackson	SC	38983	Renovate B9810 Training Bldg Finishes, Elect, Plumbing	Mar-10
Army	Fort Jackson	SC	38984	Repair 2179 Admin Area Finishes, HVAC, Elect, Latrines	Mar-10
Army	Fort Jackson	SC	39319	Renovate Child Development Center	Mar-10
Army	Fort Jackson	SC	39320	Renovate Daniel Circle Chapel, B 3350	Mar-10
Army	Fort Jackson	SC	39325	Repair Starr Hall B3270	Mar-10
Army	Corpus Christi Army Depot	TX	38360	Repair HVAC, Elect, Plumbing, Finishes B1727 Barracks	Mar-10
Army	Fort Bliss	TX	30683	Install A Precooling System and Switch to the 20mw Backup Generator at Chaffee and Job Stuart	Mar-10
Army	Fort Sam Houston	TX	38887	Design / Construct Laundry Room Addition to Barracks 904	Mar-10
Army	Dugway Proving Ground	UT	33517	Install Stationary Generator, Dining Facility (Bldg 4545)	Mar-10
Army	Dugway Proving Ground	UT	33539	Replace Generator, Ditto Communications Center	Mar-10
Army	Dugway Proving Ground	UT	33540	Replace Roof, Provost Marshall Office	Mar-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Army	Dugway Proving Ground	UT	33541	Upgrade Electrical Service, Main Gate	Mar-10
Army	Dugway Proving Ground	UT	33542	Upgrade Electrical Service, Post Office	Mar-10
Army	Dugway Proving Ground	UT	38329	Install Blast Resistant Windows Bldg 3236	Mar-10
Army	Fort Belvoir	VA	39205	Replace central steam heat with individual boilers--6 bldgs	Mar-10
Army	Fort Belvoir	VA	39287	Replace central steam heat with individual boilers--2 bldgs	Mar-10
Army	Fort Lee	VA	32992	Construct small Fitness Center at Ordinance School	Mar-10
Army	Fort Myer	VA	17816	Replace Air Handling Unit (AHU) and Controls bldg P-73	Mar-10
Army	Fort Myer	VA	24098	Install HVAC, Server Rooms, Bldg 205 and Bldg 238	Mar-10
Army	Fort Myer	VA	31596	Replace Fire Alarm Transmitter System	Mar-10
Army	Fort Myer	VA	35963	Replace central steam heat with individual boilers--multiple bldgs	Mar-10
Army	Fort Lewis	WA	33406	Major Range Road Repairs	Mar-10
Army	Fort Lewis	WA	34148	Repair Heat Distribution Piping 3100 Block	Mar-10
Army	Fort Lewis	WA	34149	Repair Heat Distribution Piping 3200 Block	Mar-10
Army	Fort Lewis	WA	34165	Repair/replace Transformers and Vaults, Bldg 3746	Mar-10
Army	Camp Villere	LA	22200812097	Repair/upgrade Barracks (Bldg 0403) to Current HVAC and Electrical Standards	Mar-10
Army	Lake Charles	LA	NULL	Repair Roof at Field Maintenance Shop (FMS 11)	Mar-10
Army	Plaquemine	LA	NULL	Repair Roof at Field Maintenance Shop (FMS15)	Mar-10
Army	Pine Bluff Arsenal	AR	38976	Demolish Housing Infrastructure	Mar-10
Army	Pine Bluff Arsenal	AR	38968	Repair Fencing, Restore Grounds	Mar-10
Army	Iowa Army Ammunition Plant	IA	38919	Repair Housing Interiors	Mar-10
Army	Natick Soldier Systems Labs	MA	38582	Repair Sewers	Mar-10
Army	Natick Soldier Systems Labs	MA	38587	Replace Heating Systems	Mar-10
Army	Natick Soldier Systems Labs	MA	38592	Replace Windows	Mar-10
Army	Fort Belvoir	VA	38575	Upgrade Housing Services Office	Mar-10
Army	Yuma Proving Ground	AZ	33485	Repair Admin Buildings 306 & 308-Flooring, Windows, HVAC, Finishes.	Mar-10
Army	Aberdeen Proving Ground	MD	37563	Repair Elevator Palm Push Pads, E3330	Mar-10
Army	Fort Leonard Wood	MO	38868	Replace Cooling Tower @ B1021	Mar-10
Army	Fort Jackson	SC	30033	Repair Findings Identified By Commissioning at Various Buildings	Mar-10
Army	Fort Rucker	AL	30947	Repair HVAC - Training Barracks	Mar-10
Army	Fort McNair	DC	35961	Relamp NDU Bldgs, McNair	Mar-10
Army	Fort Stewart	GA	28409	Renovate Lift Station - Hunter Army Air Field	Mar-10
Army	Fort Bragg	NC	26972	Replace Failing Bridge T8520, Camp Mackall	Mar-10
Army	Fort Bragg	NC	29900	Install Ground Source Heat Pump, Bldg 3-3327	Mar-10
Army	Fort Bragg	NC	32292	Repair/Renovate Building: A-3275 to Support Joint Mobilization/Redeployment Center	Mar-10
Army	Fort Bragg	NC	34512	Repair Bldg, C-4329, Bde Hq For 1st Bct	Mar-10
Army	Fort Hamilton	NY	27664	Repair Elevator, Bldg 114 Admin	Mar-10
Army	Dugway Proving Ground	UT	38328	Construct Mobile Command Post Garage	Mar-10
Army	Dugway Proving Ground	UT	38382	Install Access Control Point Overhead Cover	Mar-10
Army	Fort Buchanan	PR	74229	Repair Substation (Brown Feeder Repairs)	Mar-10
Army	Fort Buchanan	PR	74649	Roof and Exterior Repairs, Army Reserve Center (Aguadilla, PR)	Mar-10
Army	Fort McCoy	WI	Multiple	Repair Asphalt Roads	Mar-10
Army	Camp Atterbury	IN	18080215	Reconstruct Company Admin/Supply Building (Bldg 206) Totally Destroyed by June 2008 Tornadoes	Mar-10
Defense-Wide	Fort Riley	KS	48	Repair 2nd Floor Fire Penetration Life Safety Building 600 Irwin Army Community Hospital	Mar-10
Army	Fort Lewis	WA	38942	Repair Small Arms Range #105	Mar-10
Army	Fort Lewis	WA	38945	Repair Small Arms Range #106	Mar-10
Army	Fort Lewis	WA	38947	Repair Small Arms Range #107	Mar-10
Army	Fort Lewis	WA	38948	Repair Small Arms Range #108	Mar-10
Army	Fort Lewis	WA	38950	Repair Small Arms Range #109	Mar-10
Army	Fort Lewis	WA	38951	Repair Small Arms Range #110	Mar-10
Army	Fort Campbell	KY	32814	Refurbish Finishes, Elect, HVAC, Barracks Bldg 6929	Mar-10
Army	Fort Campbell	KY	34953	Repair Admin Bldgs 6747, 6748 6741--HVAC, Paint, door/window, latrines	Mar-10
Army	Fort Lewis	WA	39502	Repair Small Arms Range #111	Mar-10
Army	Fort Lewis	WA	39503	Repair Small Arms Range #112	Mar-10
Army	Fort Lewis	WA	39504	Repair Small Arms Range #113	Mar-10
Army	Volunteer Training Site Catoosa	GA	47009003	Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-08)	Mar-10
Army	Volunteer Training Site Catoosa	GA	47009004	Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-09)	Mar-10
Army	Volunteer Training Site Catoosa	GA	47009005	Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-10)	Mar-10
Army	Volunteer Training Site Catoosa	GA	47009006	Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-11)	Mar-10
Air Force	Wright Patterson AFB	OH	ZHTV0819032	Repair Walls Bldg 11420, Ph 2: AF Band of Flight Fac	Mar-10
Army	Fort Benning	GA	33119	Repair & Upgrade Storm Sewer - Wold to Ingersoll	Mar-10
Army	Tobyhanna Army Depot	PA	37861	Renovate First Floor Barracks 230 Bathrooms	Mar-10
Defense-Wide	Fort Meade	MD	72	Repair/Replace Elevators	Mar-10
Army	Fort Rucker	AL	39281	Construct Mail Distribution Center	Mar-10
Army	Esler Field	LA	NULL	Repair Roof at Unit Training and Equipment Site (Bldg 6065)	Mar-10
Defense-Wide	Fort Rucker	AL	5	Repair Simulator Test Facility, US Army Aeromedical Research Laboratory	Mar-10
Air Force	Tinker AFB	OK	WYWK090227	Restripe Parking Areas For Fire, Safety & ATFP	Mar-10
Air Force	Tinker AFB	OK	WYWK090226	Maintain Parking Lot Striping	Mar-10
Air Force	Tinker AFB	OK	WYWK090236	Maintain Exterior (Bldg 289)	Mar-10
Air Force	Arnold AFB	TN	ANZY030038	Construct Communications Facility - Cable Node	Mar-10
Air Force	Tyndall AFB	FL	XLWU012056D	Replace and Add Gas Release Valves On Sewer Discharge Main	Mar-10
Air Force	Tyndall AFB	FL	XLWU012056A	Repair Airfield Drainage, Phase 1	Mar-10
Air Force	Hanscom AFB	MA	MXRD090040C	Repair Vandenburg Drive And Langley Road	Mar-10
Army	Fort Leonard Wood	MO	38842	Provide Air Conditioning System for Gyms - 600, 700, & 800 Areas	Mar-10
Army	Fort McNair	DC	32561	Correct Road Deficiencies and Widen 5th Ave, McNair	Mar-10
Army	Military Ocean Terminal Sunny Point	NC	38610	Repair Wharf	Mar-10
Army	Fort Myer	VA	38723	Replace Failing HVAC Equipment bldg 313 directorate of logistics maintenance facility	Mar-10
Army	Aurora	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Aurora / BAFB	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Aurora / BAFB	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Longmont	CO	80212	Bring Readiness Center/CSMS Up to Current Energy Standards	Mar-10
Army	Denver	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Army	Fort Carson	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Golden	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Golden	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Grand Junction	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Gypsum	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Rocky Ford	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Sterling	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Watkins	CO	80212	Bring Readiness Center Up to Current Energy Standards	Mar-10
Army	Muscatatuck Urban Training Center	IN	18080257	Replace Roof , Windows, Doors, Mechanical and Electrical Systems, and Fire Suppression System at Building 30 (Communications Building)	Mar-10
Defense-Wide	US Army Soldier Systems Center Natick	MA	51	Repair Soldier Performance Lab	Mar-10
Defense-Wide	Fort Eustis	VA	129	Renovate Utilities Veterinary Buildings 2788/2790	Mar-10
Air Force	Robins AFB	GA	UHHZ080183	Repair Chapel HVAC System (Bldg 769)	Mar-10
Army	Fort Hamilton	NY	36417	Remodel Building 402, Fitness Center-Restore All Finishes and Systems	Mar-10
Army	McAlester Army Ammunition Plant	OK	29889	Electric Utility Repair	Mar-10
Army	Carlisle Barracks	PA	38312	Energy Efficiency Upgrades for Building 452	Mar-10
Army	Carlisle Barracks	PA	38311	Energy Efficiency Upgrades for Building 314	Mar-10
Army	Carlisle Barracks	PA	38309	Energy Efficiency Upgrades at Building 330	Mar-10
Army	Carlisle Barracks	PA	26236	Replace High Voltage Cables on Main Loop	Mar-10
Army	Tobyhanna Army Depot	PA	22763	Db Water Dist Sys Restoration & Upgrade	Mar-10
Army	Fort Lewis	WA	30093	Replace Stacks on Three Boiler Plants	Mar-10
Army	Fort Lewis	WA	34137	Repair Railroad Ave- Mann to Alder	Mar-10
Army	Fort Lewis	WA	34133	Repair 12th St from Pendleton to Bitar Ave.	Mar-10
Army	Fort Lewis	WA	22456	Install 3 Stack Economizers in Existing Boiler Stacks	Mar-10
Army	Fort Lewis	WA	34131	Repair Pendleton Ave Between Main St to Lewis Dr	Mar-10
Army	Fort Lewis	WA	34150	Add Right Turn Lane to West Way Intersecting Clark Road	Mar-10
Army	Fort Lewis	WA	22448	Install Stack Economizers in Existing Boiler Stacks	Mar-10
Army	Fort Richardson	AK	28620	Repair Water and Electrical Systems	Mar-10
Army	Fort Richardson	AK	32379	Bldg 664, UPH, Repair Interior for 62 Truck Company	Mar-10
Army	Fort Richardson	AK	33909	Construct addition to motor pool bldg B47645	Mar-10
Army	Fort Richardson	AK	35221	Install Lighting Controls Bldg 800	Mar-10
Army	Fort Richardson	AK	35365	Install Lighting and Controls Bldg 802	Mar-10
Army	Fort Richardson	AK	38812	Repair & Upgrade Vent System B806	Mar-10
Army	Fort Rucker	AL	34802	Install Air Conditioning to Communication Rooms	Mar-10
Army	Fort Rucker	AL	34834	Convert Electrical and Gas Meters to Advanced Metering Kits	Mar-10
Army	Fort Rucker	AL	34836	Replace Digital Controls - B5102	Mar-10
Army	Fort Rucker	AL	34843	Replace Digital Controls - B9214	Mar-10
Army	Fort Carson	CO	25843	Remove/Replace Bridge No. T85115	Mar-10
Army	Fort Carson	CO	37499	Upgrade Barracks 7480-Repair Finishes, Elect, HVAC, Latrines, Doors, Windows.	Mar-10
Army	Fort Carson	CO	38543	Repair DFAC, 7481 For 10th Sfg	Mar-10
Army	Fort Carson	CO	38905	Repair interior, bldg 8030 Floors, Finishes, Latrines, HVAC, Elect.	Mar-10
Army	Blue Grass Army Depot	KY	22081	Renovate Barracks 162-- Walls, HVAC, Electrical, Plumbing, Finishes	Mar-10
Army	Blue Grass Army Depot	KY	31797	Repair and Upgrade Sewer Treatment Plant	Mar-10
Army	Blue Grass Army Depot	KY	31798	Water Plant & Distribution Lines Repair and Upgrades	Mar-10
Army	Blue Grass Army Depot	KY	38930	Repair Failed Building Exterior siding and roofs, multiple buildings.	Mar-10
Army	Blue Grass Army Depot	KY	38932	Repair Ceiling Insulation (Bldgs 216,221 & 222)	Mar-10
Army	Natick Labs	MA	31540	Replace Boilers Bldgs 1,2,3 & 4	Mar-10
Army	Natick Labs	MA	31541	Repair Building 20 Exterior Surfaces	Mar-10
Army	Fort Meade	MD	13428	Repair/Replace HVAC at Fitness Facility	Mar-10
Army	Fort Meade	MD	13432	Repair Admin Building 6530 finishes, doors, windows, HVAC, masonry	Mar-10
Army	Fort Meade	MD	13433	Repair/Replace of HVAC and Controls 4550	Mar-10
Army	Fort Meade	MD	13829	Repair/Replace of HVAC and Controls 4551	Mar-10
Army	Fort Meade	MD	13858	Repair Heat and Air Units Barracks 4704	Mar-10
Army	Fort Meade	MD	16749	Replace HVAC Bldg 6330	Mar-10
Army	Fort Meade	MD	19803	Replace Controls For HVAC In Mechanical Room	Mar-10
Army	Fort Meade	MD	22364	Repair/Replacement of HVAC System and Controls, Exterior Painting 8550	Mar-10
Army	Fort Meade	MD	24826	Repair Ernie Pyle/Reece Road Intersection	Mar-10
Army	Fort Meade	MD	38058	Replace HVAC System Bldg 03100	Mar-10
Army	Fort Meade	MD	38059	Replace HVAC System Bldg 4725	Mar-10
Army	Fort Meade	MD	38234	Replace Heat and Air Units Barracks Bldg 4703	Mar-10
Army	Fort Meade	MD	38235	Replace Heat and Air Units Barracks Bldg 4707	Mar-10
Army	Fort Meade	MD	38236	Replace Heat and Air Units Barracks Bldg 4709	Mar-10
Army	Fort Meade	MD	38237	Replace Broken Pneumatic Controls With Digital Controls	Mar-10
Army	Fort Meade	MD	38238	Install 7 Variable Air Volume Boxes and Associated Ductwork and Piping; Replace Outdoor Condensing Unit and Coil. Repepe Boiler	Mar-10
Army	Fort Meade	MD	38243	Replace HVAC With 4-Pipe System. Install Ventilation. Reuse Chiller and Boiler - Barracks Bldg 4415	Mar-10
Army	Fort Meade	MD	38248	Replace Air Cooled Chiller and Building Loop Circulation Pumps Bldg 8544	Mar-10
Army	Fort Meade	MD	38249	Bldg 8544 Repairs For Outside Air and Moisture Control	Mar-10
Army	Fort Leonard Wood	MO	38863	Repair Primary and Secondary Digester at sewage treatment plant	Mar-10
Army	Fort Hamilton	NY	2573	Replace HVAC With Geothermal Energy For Bldg 209	Mar-10
Army	Fort Hamilton	NY	32468	Construct Geo-Thermal Plant Near Bldg 301	Mar-10
Army	Fort Hamilton	NY	32521	Construct Geo-Thermal Plant Near B302	Mar-10
Army	Fort Sill	OK	19393	Replace Runway Lighting at Henry Post Army Airfield	Mar-10
Army	Fort Sill	OK	22371	Rpr Components of Electrical Substation - Bd 1888 (DPW)	Mar-10
Army	Fort Sill	OK	22374	Bldg 3040 Central Plant Mechanical Equipment	Mar-10
Army	Fort Sill	OK	22554	Repair/Replace Components Feeders 6&7 (DPW)	Mar-10
Army	Fort Sill	OK	22559	Repair/Replace Electrical Distribution System Feeders, West Range	Mar-10
Army	Fort Sill	OK	22561	Bd 730 Rpr Central Plant Mechanical Equipment (DPW)	Mar-10
Army	Fort Sill	OK	23659	Construct Ph 1 Waste Water Recycling Distribution Network	Mar-10
Army	Fort Sill	OK	29956	Building 730 Central Heating and Cooling Distribution System (FAS)	Mar-10
Army	Fort Sill	OK	30180	Replace 2 Each Back-Up Generators, Electrical Distribution System (DPW)	Mar-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Army	Fort Sill	OK	32476	Replace Energy Management Control System (DPW)	Mar-10
Army	Fort Sill	OK	34294	Repair Bathrooms and Building Components B700 Knox Hall	Mar-10
Army	Fort Sill	OK	35873	Bldgs 59, 60, 700, 3164, 6011, 6036 repair/replace All Life Safety Systems (Postwide)	Mar-10
Army	Fort Sill	OK	37500	D6240-Repair Lake George Dam.	Mar-10
Army	Fort Sill	OK	37805	Repair B730 Snow Hall--HVAC, plumbing, electrical, fire protection, Latrines, classrooms, lighting finishes	Mar-10
Army	Carlisle Barracks	PA	18660	Replace the HVAC Air Handlers @ B-122	Mar-10
Army	Carlisle Barracks	PA	26109	Install Potable Water Distribution line to B-950	Mar-10
Army	Carlisle Barracks	PA	26110	Water Plant/Distribution Evaluation and Upgrades	Mar-10
Army	Carlisle Barracks	PA	37887	Upgrade Lighting in B-632	Mar-10
Army	Carlisle Barracks	PA	38057	Replace All Lighting In B-122	Mar-10
Army	Carlisle Barracks	PA	38536	Re-Commission Building 950 For Energy Conservation	Mar-10
Army	Fort Hood	TX	33441	Repair Building 422 Finishes, Electrical, Plumbing, HVAC, Fire Protection, Doors	Mar-10
Army	Fort Lewis	WA	39270	Replace Stack On Boiler Plant 3292	Mar-10
Army	Fort Lewis	WA	39271	Replace Stack On Boiler Plant 9580	Mar-10
Army	Tobyhanna AD	PA	20648	Renovate Sun Rooms	Mar-10
Army	Tobyhanna AD	PA	38677	Replace Porch Covers and Supports, Senior NCO Family Housing Units, No. 500 - 509	Mar-10
Air Force	Francis E Warren AFB	WY	GHLN091035	Construct Target Storage Fac Outdoor Firing Range Bldg 1591	Mar-10
Air Force	Francis E Warren AFB	WY	GHLN081081	Repair/Interim Upgrade Outdoor Firing Range Bldg 1591	Mar-10
Air Force	Wright Patterson AFB	OH	ZHTV081899	Replace First Floor Lighting (Bldg 20024)	Mar-10
Air Force	Wright Patterson AFB	OH	ZHTV091971	Replace Electrical Feed to Multiple AFIT Facilities	Mar-10
Air Force	Francis E Warren AFB	WY	GHLN082019	Repair/Replace Water Well, MAFA-01/F-01/O-01	Mar-10
Air Force	Patrick AFB	FL	SXHT021047	Replace Electrical Circuits for Runway 11/29	Mar-10
Army	Fort Huachuca	AZ	35812	Repair Wastewater Treatment Plant Digester Lid to Prevent Methane Gas Escape	Mar-10
Army	Fort Riley	KS	38836	Renovate Building 219 Des	Mar-10
Army	Detroit Arsenal	MI	30238	Install New Eastside Water Main for Fire Protection & Potable Water Lines	Mar-10
Army	Schofield Barracks	HI	39394	Install Solar Powered Security Light	Mar-10
Army	Fort Bragg	NC	34728	Renovate Bldg 2-1246	Mar-10
Army	Fort Sill	OK	39175	Bldg 462-Replace All Over Head Electrical Service With Pad-Mounted Transformer Service.	Mar-10
Army	Litchfield Armory	IL	170615A	Unit Supply, Locker Rm Add/Alt	Mar-10
Army	Litchfield Armory	IL	17080310	Upgrade Electrical System	Mar-10
Army	Sullivan Readiness Center	IL	17080309	Upgrade Elec Sys	Mar-10
Army	West Frankfort Readiness Center	IL	17080224	Unit Supply, Locker Rm Add/Alt	Mar-10
Army	West Frankfort Readiness Center	IL	17080311	Upgrade Electrical System	Mar-10
Army	DSCC Building 24	OH	3909003	DSCC Building 11 Sec 10 Upgrades	Mar-10
Army	Volunteer Training Site Milan	TN	47090022	Repair/Upgrade Readiness Center HVAC to Current Building Standards	Mar-10
Defense-Wide	Fort Riley	KS	47	Modernize Dental Facility Building 7670	Mar-10
Defense-Wide	US Army Soldier Systems Center Natick	MA	50	Repair Fire Sprinkler Protection System	Mar-10
Defense-Wide	Fort Lee	VA	133	Modernize Radiology/Laboratory Departments	Mar-10
Defense-Wide	NAVMEDCEN Portsmouth	VA	142	Replace Roof and Repair Exterior Building Medical Admin Building-3	Mar-10
Defense-Wide	Fort Lewis	WA	153	Repair Radiology Clinic Air Handling Unit	Mar-10
Navy	New Haven	CT	RM-115-09	Center & Site Repairs	Mar-10
Air Force	Nellis AFB	NV	RKMF090043	Repair Water Main, Bldg 625	Mar-10
Air Force	Nellis AFB	NV	RKMF080068	Repair H-Frame Xfms, Ncc Bldg 589	Mar-10
Air Force	Arnold AFB	TN	ANZY060064	Construct Loading Dock Extension (Bldg 1476)	Mar-10
Air Force	Arnold AFB	TN	ANZY020009	Construct Oil Drum and Bromine Trailer Storage Facility	Mar-10
Air Force	Cape Canaveral AS	FL	DBEH011683	Repair HVAC Sys: Satellite Assembly Bldg Annex	Mar-10
Army	Fort Greely	AK	32551	Upgrade Sprinkler Sys Commissary	Mar-10
Army	Fort Greely	AK	35526	Construct Two Meteorology Towers to Collect Wind Data	Mar-10
Army	Fort Greely	AK	34975	Install Communication Lines in Building 601	Mar-10
Army	Fort Greely	AK	32552	Fill 2 Hydraulic Lift Bays	Mar-10
Army	Fort Richardson	AK	38264	LED Street Lights	Mar-10
Army	Fort Richardson	AK	38268	Wind Data Test Towers	Mar-10
Army	Pine Bluff Arsenal	AR	38700	Repairs Building, 63-100 Transite Roof	Mar-10
Army	Pine Bluff Arsenal	AR	38699	Upgrade Fire Protection Sys Building 33-630	Mar-10
Army	Fort Irwin	CA	37217	Repair Kitchen Ventilation System Building 1317	Mar-10
Army	Fort Irwin	CA	38778	Repair Infant Playground Area	Mar-10
Army	Fort Irwin	CA	38765	Repair Pre-School Playground Area	Mar-10
Army	Fort Stewart	GA	34634	Repair Sprinkler Risers - IPB #2	Mar-10
Army	Fort Riley	KS	32446	Repair Deficiencies on airfield Levee	Mar-10
Army	Fort Riley	KS	31680	Replace Or Repair Pump at 393	Mar-10
Army	Fort Riley	KS	33398	Repair Roof Normandy Chapel, Type: 73017, Building 7865, Religious	Mar-10
Army	Fort Knox	KY	38783	Replace Windows in Building, 5918	Mar-10
Army	Fort Leonard Wood	MO	38847	Replace Air Conditioning Systems in Specker Admin Facs	Mar-10
Army	West Point Mil Reservation	NY	34970	Repairs to Mine Lake Dam	Mar-10
Army	McAlester Army Ammunition Plant	OK	29890	Water Main Utility Repair	Mar-10
Army	Fort Jackson	SC	30029	Resurface Wildcat Road	Mar-10
Army	Fort Lewis	WA	32582	Repair Primary Treatment Clarifiers at Wastewater Treatment Plant	Mar-10
Army	Fort Irwin	CA	37214	Repair family Support bldg 1313--Finishes, roof, doors, windows, HVAC, electrical, restrooms	Mar-10
Army	Fort Irwin	CA	39235	Repair HVAC Units - Augmentee Barracks	Mar-10
Army	Fort Irwin	CA	39244	Repair Billets and Latrine/Shower Reserve Component	Mar-10
Army	Wheeler Army Airfield	HI	38427	Repair 3rd Floor B107	Mar-10
Army	Wheeler Army Airfield	HI	38453	Building B102 Dining Facility--install pads, conduit, switchgear for backup Generator	Mar-10
Army	Fort Sill	OK	31018	Bldg 900/912/913/914 Install Fire Rated Doors	Mar-10
Army	Fort Sill	OK	37609	Bldg 707-Install Bars On Supply Windows/Doors.	Mar-10
Army	Fort Bliss	TX	23094	Repair Vehicular Pavements, Combat Aviation Brigade	Mar-10
Army	Fort Bliss	TX	39286	Repair Airfield Pavement to Eliminate Hazards Phase I	Mar-10
Army	Fort Myer	VA	30278	Renovate Bldg 249 Company Operations	Mar-10
Army	Portland Armory, FMS	ME	23SR09-441	Field Maint Shop 1 High Efficiency Boiler Installation	Mar-10
Army	Rickenbacker (MTA)	OH	3909006	Waterline Renovation	Mar-10
Defense-Wide	Fort Benning	GA	27	Modernize Ortho, Peds, Int Med Building 09200 Martin Army Hospital	Mar-10
Defense-Wide	Fort Knox	KY	49	Modernize Emergency Department	Mar-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Defense-Wide	Aberdeen Proving Ground	MD	71	Modernize Kirk Army Health Clinic	Mar-10
Defense-Wide	Fort Meade	MD	74	Repair Electrical Service & HVAC	Mar-10
Defense-Wide	WRAIR - Forest Glen	MD	84	Repair Research Labs in Building 503 -Walter Reed Army Institute of Research	Mar-10
Defense-Wide	WRAIR - Forest Glen	MD	87	Repair HVAC System in Lab Building 511 - Walter Reed Army Institute of Research	Mar-10
Defense-Wide	WRAIR - Forest Glen	MD	88	ADA Accessibility Building 503 - Walter Reed Army Institute of Research	Mar-10
Defense-Wide	WRAIR - Forest Glen	MD	89	ADA Restroom Conversion Building 503/511 - Walter Reed Army Institute of Research	Mar-10
Defense-Wide	WRAIR - Forest Glen	MD	90	Repair Bio Safety Lab-3 Building 503 - Walter Reed Army Institute of Research	Mar-10
Defense-Wide	Carlisle Barracks	PA	105	Repair Dental Clinic	Mar-10
Defense-Wide	Fort Sam Houston	TX	123	Repair ENT & Ophthalmology Clinics	Mar-10
Defense-Wide	Fort Lewis	WA	144	Modernize Medical Information Management Division Computer Room, Madigan Army Medical Center	Mar-10
Defense-Wide	Fort Lewis	WA	150	Repair Interstitial Deck, Madigan Army Medical Center	Mar-10
Air Force	Buckley AFB	CO	CRWU081059	Construct Wing HQ Assembly Area	Apr-10
Air Force	Hanscom AFB	MA	MXRD090040D	Repair Intersection: Barksdale & Forbes To Vandenberg	Apr-10
Air Force	Hanscom AFB	MA	MXRD090040F	Repair Barksdale Between Forbes through Grenier to Eglin	Apr-10
Air Force	Hanscom AFB	MA	MXRD090040E	Repair Barksdale Between Grenier & Gate 4; Rpr Kirtland	Apr-10
Air Force	Minot AFB	ND	QJVF080124	Construct Parking Lot (Bldg 679)	Apr-10
Air Force	Minot AFB	ND	QJVF076002	Repair Fencing	Apr-10
Army	Fort Gordon	GA	38299	Repair Roof, Youth Services Building	Apr-10
Army	Fort Gordon	GA	16369	Dredge Reservoir, Mirror Lake	Apr-10
Defense-Wide	Fort Irwin	CA	9	Medical Warehouse Addition	Apr-10
Air Force	Kaena Point Satellite Tracking Station	HI	LXHY490109	Repair/Onstruct Potable Water System, Kpsts	Apr-10
Air Force	Kaena Point Satellite Tracking Station	HI	LXHY081004	Replace Dillingham Waterline	Apr-10
Air Force	Tinker AFB	OK	WVYK090235	Maintain Exterior Of Child Devel. Ctr (B5510 & B5520)	Apr-10
Air Force	Tinker AFB	OK	WVYK090225	Maintain Street Striping: Various Locs Basewide	Apr-10
Air Force	Tinker AFB	OK	WVYK090189	Widen Lanes At Multiple Locations Along Arnold Blvd	Apr-10
Air Force	Tinker AFB	OK	WVYK090188	Repair Pavement: Arnold Blvd Between Air Depot & Ave A	Apr-10
Air Force	Tinker AFB	OK	WVYK070180	Repair Configure Intersection Of Arnold St & H Avenue	Apr-10
Air Force	Hanscom AFB	MA	UQHH090040A	Repair Paving - Sagamore Hill Parking Lot	Apr-10
Air Force	Hanscom AFB	MA	UQHH090040B	Repair Entrance Driveway/Upgrade Drainage at Sagamore Hill	Apr-10
Army	MTA Camp Shelby	MS	28090051	Upgrade Building Systems 2900 Block	Apr-10
Army	MTA Camp Shelby	MS	28090052	Upgrade Building Systems 3100 Block	Apr-10
Army	MTA Camp Shelby	MS	28090050	Upgrade Building Systems 2800 Block	Apr-10
Army	MTA Camp Shelby	MS	28090049	Upgrade Building Systems 2700 Block	Apr-10
Army	MTA Camp Shelby	MS	28090045	Upgrade Building Systems 2100 Block	Apr-10
Army	MTA Camp Shelby	MS	28090048	Upgrade Building Systems 2500 Block	Apr-10
Army	MTA Camp Shelby	MS	28090047	Upgrade Building Systems 2400 Block	Apr-10
Army	MTA Camp Shelby	MS	28090046	Upgrade Building Systems 2300 Block	Apr-10
Army	MTA Camp Shelby	MS	28090044	Upgrade Building Systems 2000 Block	Apr-10
Army	MTA Camp Shelby	MS	28090043	Upgrade Building Systems 1900 Block	Apr-10
Army	MTA Camp Shelby	MS		Upgrade Building Systems 1400 Block	Apr-10
Army	MTA Camp Shelby	MS		Upgrade Building Systems 1500 Block	Apr-10
Army	MTA Camp Shelby	MS		Upgrade Building Systems 1600 Block	Apr-10
Army	MTA Camp Shelby	MS		Upgrade Building Systems 1700 Block	Apr-10
Army	MTA Camp Shelby	MS		Upgrade Building Systems 1800 Block	Apr-10
Army	Fort Leonard Wood	MO	38834	Replace Boilers - 600, 700, & 800 Areas	Apr-10
Army	Frankfort	IN	18080179	Replace Roof at Readiness Center	Apr-10
Army	Bismarck RJB Complex	ND		Upgrade Electrical System at Readiness Center	Apr-10
Air Force	Wright Patterson AFB	OH	ZHTV091886D	Construct Drop Arm-Gate 12a (20761)	Apr-10
Army	Muncie	IN	18080178	Replace Roof at Readiness Center	Apr-10
Army	Camp Atterbury	IN	18090135	Replace Sewer Lines	Apr-10
Air Force	Schriever AFB	CO	GLEN091016	Install Ground Source Heat Pumps	Apr-10
Air Force	Kelly Field Annex	TX	MPLS071012AQ	Mtn (Paint) Floors In Hangar (B935)	Apr-10
Air Force	Tinker AFB	OK	WVYK040098E	Replace Multiple Spill Containment Pond Liners	Apr-10
Air Force	Tinker AFB	OK	WVYK050537	Repair Cathodic Protection System For Storage Tanks	Apr-10
Air Force	Lackland AFB	TX	MPLS091010R	Repair-Reconstruct Luke Rd (Barnes to Carswell)	Apr-10
Air Force	Sheppard AFB	TX	VNVP981008	Relocate overhead Electric to underground Pole Way 4th Ave	Apr-10
Army	Cape May	NJ	34CM901	Replace Field Maint Shop Lighting	Apr-10
Army	Dover Picatinny Arsenal	NJ	34PI901	Replace Field Maint Shop Lighting	Apr-10
Army	Fort Dix TS	NJ	34FD903	Replace Field Maint Shop Lighting	Apr-10
Army	Hackettstown	NJ	34HT601	Replace HVAC	Apr-10
Army	Teaneck	NJ	34TN901	Replace Field Maint Shop Lighting	Apr-10
Army	Vineland	NJ	34VL901	Replace Field Maint Shop Lighting	Apr-10
Army	Westfield	NJ	34WF901	Replace Field Maint Shop Lighting	Apr-10
Army	Camp Grafton	ND		Install Soot Blowers at Central Heat Plant	Apr-10
Defense-Wide	Fort Gordon	GA	30	Repair Podiatry/Ortho Clinics Building 00300	Apr-10
Defense-Wide	Fort Lewis	WA	155	Repair Pond Supply Diversion Line, Madigan Army Medical Center	Apr-10
Army	Fort Myer	VA	32559	Bldg. 301 Repair Distribution Pump Station	Apr-10
Air Force	Nellis AFB	NV	RKMF080043	Repair HVAC Multiple Facilities	Apr-10
Army	Fargo	ND		Replace Lighting at Field Maintenance Shop	Apr-10
Army	Grand Forks	ND		Replace Lighting at Field Maintenance Shop	Apr-10
Army	Camp Grafton	ND		Replace Lighting at Unit Training and Equipment Site	Apr-10
Air Force	Wright Patterson AFB	OH	ZHTV980039A	Repair/Replace Apron - (A-7)	Apr-10
Air Force	Wright Patterson AFB	OH	ZHTV032806	Resurface Roads Parking Lots By Warehouses 257 and 258	Apr-10
Army	Camp Perry Training Site (CTC)	OH	3909035	Electric Distribution Upgrade	Apr-10
Army	Fort Pickett ARNG MTC	VA	510341	Replace Energy Inefficient Building Components	Apr-10
Army	Volunteer Training Site Catoosa	GA	47090047	Repair Water and Water Sewer System	Apr-10
Air Force	Cannon AFB	NM	CZQZ094018	Repair HVAC System B74	Apr-10
Army	Centennial	CO	80208	Joc Heat Pump System	Apr-10
Army	Stout Field Indianapolis	IN	18080152	Energy	Apr-10
Army	Camp Swift	TX	NULL	Structural Repair & Renovation, Building 221	Apr-10
Army	Camp Swift	TX	NULL	Structural Repair & Renovation, Building 231	Apr-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Army	Camp Swift	TX	NULL	Structural Repair & Renovation, Building 252	Apr-10
Army	Camp Swift	TX	48090305	Repair/upgrade 31 Barracks to Current HVAC and Electrical Standards	Apr-10
Army	Hillsborough FMS	NH	1153	Replace Plumbing	Apr-10
Army	Hillsborough FMS	NH	1154	Refloor center	Apr-10
Army	Hillsborough FMS	NH	1155	Replace Existing Windows	Apr-10
Army	Littleton FMS	NH	1156	Replace Plumbing	Apr-10
Army	Littleton FMS	NH	1157	Resurface and Restripe Organizational Parking	Apr-10
Army	Littleton FMS	NH	1158	Refloor center	Apr-10
Army	Littleton FMS	NH	1159	Replace Existing Windows	Apr-10
Army	Manchester FMS	NH	1160	Replace Plumbing	Apr-10
Army	Manchester FMS	NH	1161	Refloor center	Apr-10
Army	Manchester FMS	NH	1162	Replace Existing Windows	Apr-10
Army	Lakehurst TS Naval Air Station	NJ		Replace Roof at Army Aviation Support Facility	Apr-10
Air Force	Wright Patterson AFB	OH	ZHTV0818252	Repair Entrance Steps to HQ AF Research Labs(Bldg 20015)	Apr-10
Air Force	Wright Patterson AFB	OH	ZHTV0818251	Repair Entrance Steps to HQ Aero. Sys. Command (Bldg 20014)	Apr-10
Defense-Wide	Fort Leavenworth	KS	45	Repair Pharmacy	Apr-10
Defense-Wide	Aberdeen Proving Ground	MD	53	Modernize 3rd Floor Utilities - Center for Health Promotion & Preventive Medicine	Apr-10
Defense-Wide	WRAIR - Forest Glen	MD	86	Building 503 and Tunnel Area Basement Waterproofing Repair, Walter Reed Army Institute of Research	Apr-10
Defense-Wide	Fort Lewis	WA	146	Replace Emerg Gen Diesel Fuel Tanks	Apr-10
Army	Harrisburg Readiness Center	PA		Upgrade Electrical, Plumbing, and HVAC in Building #7 (readiness center) to Current Building Standards	May-10
Army	Allentown RC	PA		Replace Roof and Retrofit HVAC and Energy Management Systems at Readiness Center	May-10
Army	Fort Indiantown Gap	PA		Construct Simulations Center to Support Regional Battle Command Training Center	May-10
Army	Camp Grafton	ND		Upgrade Energy Management Control Systems at Unit Training and Equipment Site	May-10
Army	Camp Grafton	ND		Replace Roof at Unit Training and Equipment Site	May-10
Army	New Hampshire National Guard Training Site	NH	1163	Barracks(Roof Replacement, Window & Door Projects, Etc)	May-10
Army	Smr Combined Support Maintenance Shop	NH	1164	Replace Plumbing	May-10
Army	Smr Combined Support Maintenance Shop	NH	1165	Refloor center	May-10
Army	Smr Combined Support Maintenance Shop	NH	1166	Replace Existing Windows	May-10
Army	State Military Reservation	NH	1167	100% Federal Buildings Upgrades (Lighting, Flooring, Heating & Cooling)	May-10
Army	State Military Reservation	NH	1168	Camp Labonte St01 Improvement	May-10
Army	Camp Clark	MO	29090706	Repair/Upgrade Dining Facility (Bldg 400/401) to Current Fire Protection, Energy, and Food Service Standards	May-10
Army	Camp Clark	MO	29090716	Repair/Upgrade Dining Facility (Bldg 417/418) to Current Fire Protection, Energy, and Food Service Standards	May-10
Defense-Wide	Fort Detrick	MD	61	Repair Medical Labs V2 and AA2 Building 1425 - Army Medical Research Institute of Infectious Diseases	May-10
Defense-Wide	Fort Detrick	MD	62	Repair Medical Labs AR317 and AR2 in Building 1425 - Army Medical Research Institute of Infectious Diseases	May-10
Defense-Wide	Fort Detrick	MD	63	Replace RO Distribution Piping Building 1425 - Army Medical Research Institute of Infectious Diseases	May-10
Defense-Wide	Fort Detrick	MD	64	Repair Agent Contamination/Isolation Unit Building 1425 - Army Medical Research Institute of Infectious Diseases	May-10
Defense-Wide	Fort Detrick	MD	67	Repair Bio Safety Lab2 and Lab 115 Building 1301	May-10
Army	Camp Swift	TX	48091213	Upgrade Potable Water Line	May-10
Army	Camp Perry Training Site (CTC)	OH	3909034	Water Distribution Upgrade	May-10
Air Force	Silver Lake Space Surveillance Station	MS	SVRL051002	Repair Operations Building	May-10
Army	Camp Grafton	ND		Replace Furnaces and Water Heaters in Barracks Bathroom Facilities	May-10
Army	Grand Forks	ND		Replace HVAC at Readiness Center	May-10
Army	Grand Forks	ND		Replace Roof at Field Maintenance Shop	May-10
Army	Pine Bluff Arsenal	AR	22764	Steam Line Replacement Phase I	May-10
Army	Pittsburgh Hunt RC	PA		Replace Hunt Readiness Center Roof, Plumbing, and Electrical Service	Jun-10
Army	Plymouth Readiness Center	PA		Replace Boiler, HVAC, and Energy Management Systems at Readiness Center	Jun-10
Army	Wilkes Barre/ Kingston RC	PA		Replace Boiler at Readiness Center	Jun-10
Army	Minot	ND		Replace Chiller at Readiness Center	Jun-10
Army	Minot	ND		Upgrade HVAC at Readiness Center with Variable Frequency Drive	Jun-10
Army	Dugway Proving Ground	UT	33576	Repair Power Plant and Replace Failed Generators	Jun-10
Army	Edgewood Area APG	MD	24090003	Install Energy Hangar Doors	Jun-10
Army	Naval Air Station Lakehurst TS Naval Air Station	NJ	34LH804	Energy Efficient Renovation	Jun-10
Army	Lawrenceville	NJ	34LV901	Replace Field Maint Shop Lighting	Jun-10
Army	Sea Girt NJ NGTC	NJ	34SG904	Replace Field Maint Shop Lighting	Jun-10
Army	Somerset	NJ	34SO701	HVAC Replacement	Jun-10
Army	Somerset	NJ	34SO702	Window Replacement	Jun-10
Army	Somerset	NJ	34SO704	Replace Field Maint Shop Lighting	Jun-10
Army	Somerset	NJ	34SO901	Renovate Bathrooms	Jun-10
Army	Bismarck RJB Complex	ND		Replace Lighting at Readiness Center and Army Aviation Support Facility	Jun-10
Air Force	Wright Patterson AFB	OH	ZHTV071983	Replace Windows Admin Facility (Bldg 20039)	Jun-10
Army	Schofield Barracks	HI	38220	Range Control Wind/Solar Power Generation System	Jun-10
Army	Billings AFRC	MT	30R10173	Mechanical System Improvements	Jun-10
Army	Billings AFRC	MT	30R10174	Install Lighting Controls	Jun-10
Army	Billings AFRC	MT	30R10149	Install Water Recycler	Jun-10
Army	Army National Guard Aviation Support Facility 3 Bates Field Mobile	AL	105032	Seal Concrete Pavement	Sep-10
Army	Birmingham AFRC	AL	109032	Oxmoor Rd Energy Conservation	Sep-10
Army	Fort McClellan ARNG Training Center	AL	108060	Building 2 Paint	Sep-10
Army	Fort McClellan ARNG Training Center	AL	109006	Water Line Installation	Sep-10
Army	Lauris D. Graves / Talladega	AL	109028	Field Maint Shop #14 Upgrade Building Systems	Sep-10
Army	Haines City Readiness Center	FL	12207050	Repair Entire Field Maint Shop to Current Building Standards	Sep-10
Army	Lawton Mates 72 Fort Sill	OK	40C3009001	Energy System Update	Sep-10

Unawarded SRM

12 March 10

Component	Installation/Location	State	Project Number	Project Title	Estimated Contract Award Date
This project information updates the Agency plans posted on http://www.defenselink.mil/recovery/ . This is an estimate of when Department Recovery Act projects will be awarded. The Department recommends monitoring www.FedBizOpps.gov for Recovery Act work.					
Army	Draper Complex	UT	4909009	Install Exterior Lighting	Sep-10
Army	Fillmore Armory/Field Maint Shop Ws2 (So)	UT	4909010	Install Exterior Lighting	Sep-10
Army	Manti Field Maint Shop 4	UT	4909011	Install Exterior Lighting	Sep-10
Army	Bunkie	LA	22200904281	Repair Roof and Interior of Readiness Center	Sep-10
Army	Camp Beauregard	LA	22200903039	Repair Roof at Medical Clinic (Bldg 804)	Sep-10
Army	Camp Beauregard	LA	22200903049	Repair Roof at Readiness Center (Bldg 805)	Sep-10
Army	Camp Beauregard	LA	22200903046	Repair Roof at Readiness Center (Bldg 904)	Sep-10
Army	Camp Beauregard	LA	22200903035	Repair Roof at Readiness Center (Bldg 949)	Sep-10
Army	Camp Beauregard	LA	NULL	Repair Roof at Storage Building (Bldg 468)	Sep-10
Army	Camp Beauregard	LA	22200903034	Repair Roof at Barracks (Bldg 565)	Sep-10
Army	Camp Beauregard	LA	NULL	Repair Roof at Readiness Center (Bldg 631)	Sep-10
Army	Camp Beauregard	LA	NULL	Repair Roof at Headquarters (Bldg 952)	Sep-10
Army	Collax	LA	NULL	Repair Roof at Readiness Center	Sep-10
Army	Crowley	LA	NULL	Repair Doors and Windows at Readiness Center	Sep-10
Army	Dequincy	LA	NULL	Repair Electrical Systems at Readiness Center	Sep-10
Army	New Roads	LA	NULL	Repair Roof at Readiness Center	Sep-10
Army	Plaquemine	LA	NULL	Repair Roof at Readiness Center	Sep-10
Army	Sarasota Readiness Center	FL	12209039	Replace HVAC	Sep-10
Army	Lake City Readiness Center	FL	12209059	Replace electric heat with natural gas	Sep-10
Air Force	Francis E Warren AFB	WY	GHLN971120P2	Repair Electrical Distribution, "J" Circuit Option 2	Sep-10
Army	Schofield Barracks	HI	38436	Street Light Renovation, Generals Loop	Sep-10